47

DART AEROSPACE LTD	Work Order:	19536
Description: Long Step Assembly – High Skid, RH	Part Number:	704A 41 640 007
D350-591-212		
Dwg: D3070 Rev. A I	Qty:	10
PF 02-11.13		Page 1 of 2

Step	Location	Procedure	By	Date	Qty	٦
1	DC	Issue Traveller	118			٦
	-	Dwg not required	PY	03.08.27	10	
2	DC	Photocopy bluefile and type labels per PPP 704A 41 640 007 CHG001 CHG002 WK 45 WK	(X)	04.03.12	10	
3	GA \	Cut D2622-120C extrusion to 116.25" long as per Dwg D30\(\frac{1}{2}\) using cutting table setup DT8185-2A Pick: Qty Part Number Description 1 D2622-120C Extrusion Ensure wall thickness is 0.070 to 0.090	B	04/03/03	lo	
4	GA	Drill extrusion per Dwg D3070 using Jig DT8680 for rivets.	8n	04/03/03		-
5	GA	Deburr				1
6	QC5	Inspect work to Step 5	511	0-1/02/02		1
	10/0		M	04/03/03	10	
7	WA	Bevel end for welding FWD ONLY	M	04/13/03	10	
8	WA \	Weld Support using Jig DT8681, weld Fwd End Plate per QSI 004 & Dwg D3070 Pick: Qty Part Number Description Batch 1 D3063-1 Support B19555 1 D3067-1 End Plate B19558 A/R Aluminum Rod 71/3066	M	OHB363	/0	
9	GA	Grind End Plate flush	58/	4/03/04	la.	1
10	QC9	Inspect weld and work to Step 9	162	We of the		1
11	FP	Chemical conversion coat as per QSI 005 4.1	1	M.13.08	10	1
12	GA \	Assemble Leg Assembly as per Dwg D3070, D3066-1 are done Pick: Oty Part Number Description Batch D3065-041 Step Leg Assy D3066-1 Spacer MS20600AD4W4 Rivet M13767	nl	215		- K
13	QC5	Inspect work to step 12	M	04/03/16	10	
14	WA	Bevel Aft end for welding	W	04/02/11	/0	
15	WA	Inspect for foreign object per QSI 024	M	14/102/11	.10	ľ
16	WA	Weld Aft End Plate per QSI 004 & Dwg D3070 Pick: Qty Part Number Description Batch 1 D3067-1 End Plate B/9558 A/R Aluminum Rod M/3066	W	04/03/16	10	

BB 09-03-2525 POSITIVE RECALL

EFFECTIVE O4.03 15 AUTH

SOO. 66 PEF

PELEASED OZ/11/01 RF STEP NCR 748 U. Compresse CH. US: 16.16

POSITIVE S/OS

Dart Aerospace Ltd

Work Order:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector		

NCR #	748	704A 41 640 007 WORK ORDER NON-CONFORMANCE								
DATE	STEP	Description of NC section A	Intial	Corrective Action Section B	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector		
04-03-12	11	The Step was not Homogene colour "Poor awality)	ml	Redo step 11	ml 3/2	3/3/16	04.03.16	مراه الد		
	;							1		
						·	<u> </u>			

	PAR#: \\A_	Fault Category:	DQA:	Date: 04.03.29.
: Date & initial all entries		QA:	N/C Closed: NA	Date: NA.

NOTE: H:Admin-QA\ISO\forms\w/oncB.doc

DART AEROSPACE LTD	Work Order:	19536
Description: Long Step Assembly – High Skid, RH	Part Number:	704A 41 640 007
D350-591-212		
Dwg: D3070 Rev. A (Qty:	10
	_	Page 2 of 2

17	GA	Grind End Plate flush			
			SB	04/03/16	10
18	QC9 & 5	Inspect work to Step 17 – Check dimension 140.56" from Dwg D3070		64/03/16	10
19	FP	Powder Coat Gloss White (Ref: 4.3.5.1) per QSI 005 4.3	1	04.03.22	
20	FP	Wing Walk per Dwg D3070 and QSI 005 4.4 mi~087	1	046522	
21	QC3	Inspect Powder Coat and Wing Walk /	M	610,23	
22	KP	Pick: Packing Kit	77(0,0,0,	70
64.03.25	P3079-041	Qty Part Number Description Batch 4 D2182B035 Rubber Cushion B30434 8 D2274 Radius Block B30307 2 D2856-400-720 Abrasion Strip B19LH5 2 D3064-1 Clamp B3013 1 D3079-041 Support Assy B30456 4 D3080-1 Clamp B19559 2 AN3-35A Bolt M13943/M12591 10 AN4-11A Bolt M13735/M1293 4 AN960JD10 Washer M13441 20 AN960JD416 Washer M13719 2 MS21042L3 Nut (or -3) M14019 10 MS21042L4 Nut (or -4) M13376/M13630	E C	04/03/04	10
23	QC4	Inspect 100% Kit for Completeness on the W/O		of 03-25	10
24	PK	Package for shipping as per PPP 704A 41 640 007	CP	04/03/25	10
25	AC	Cost/part 239, 30	5 ur	04-03-29	/ 6
26	DC	Close W/O Z 3 9 . 3 o Inspect Level 21	A	14,03.29	10

Rev	Date	Change	Revised By	Approved
Α	02.11.01	New issue	KJ RF	
Al	03,01,14	110.71" WAS 110.56"; Dwg. Rev. 41	 	#
		D3194-241 WAS D3279-041 CHGOOZ	存	A

OS. OG.OG PEF See Dated CANCEL HOSSILLE PELEASED 02/11/02

Dart Aerospace Ltd

Work		WORK ORDER CHANGES						
Order: DATE	STEP	PROCED	URE CHANGE	Ву	Date	Qty	Approval Manuf /	Approval QC Inspector
		ι						QC Inspector
			6.					
		. • .						
	,							
Non			(001/ 000 00 NOV 00 NOV	MANOF				
NCR		,	ORK ORDER NON-CONFOR	MANCE				
DATE	STEP	Description of NC section A	Corrective Action Section B	Sign &		cation tion C	Approval Design Mgr	Approval QC Inspector
			Intial	Date				
		•			*			
					L			

NOTE: Date & initial all entries H:Admin-QA\lSO\forms\w/oncB.doc

QA: N/C Closed: _____ Date:____

Job Costing Report

Dart Aerospace Ltd. Hawkesbury

Aug 27, 2003 02:05 pm

Work Order No : 0019536

Project Name : *704A 41 640 007 Project For : WK347 Department Code: Burden Flags : NNNNNNN Work Order Type : Main WO Status : Open

Main WO Number Invoice State : Not Invoiced

House Part Number: *704A 41 640 007
Description: Heli-Access-Step, Long RH Invoice Date : Invoice Number :

Manufactured : Yes Invoice Amount: 0.00

Amount Req'd : 10
Amount Done : 0
Start Date : 08-27-03 Order Entry No :

OE Value : 0.00

Est Finish Date : 11-28-03 Act Finish Date : Est Margin : 0.000%

Drawings Reqd : No Actual Margin : 0.000% Ok for Approval :

Approval Rec'd : \$0 Posted to Finished Goods

·	Estimated	Actual	Var. %	Posted	To Post
Material Cost :	0.00	0.00	0.00	0.00	0.00
Engineering Hours :	0.00	0.00	0.00	0.00	0.00
Engineering Cost :	0.00	0.00	0.00	0.00	0.00
Production Hours :	0.00	0.00	0.00		
Production Cost :	0.00	0.00	0.00	0.00	0.00
Testing Hours ::	0.00	0.00	0.00		
Testing Cost :	0.00	0.00	0.00	0.00	0.00
OverHead Hours :	0.00	0.00	0.00		
OverHead Cost :	0.00	0.00	0.00	0.00	0.00
SubContract Hours:	0.00	0.00	0.00		
SubContract:	0.00	0.00	0.00	0.00	0.00
Misc. Hours :	0.00	0.00	0.00		
Misc. :	0.00	0.00	0.00	0.00	0.00
	=======	========	_ ======		
Burden :	0.00	0.00	0.00		
	========	=======	======		
Total Cost : :	0.00	0.00	0.00		
Margin :	0.000	0.000			
Selling Cost :	0.00	0.00			

		Estimated	Actual
Labour Hrs/Amount Done	:	0.00	0.00
Profits/(Loss)	:	0.00	0.00

And the second s					i i
			•		
•					
		·			
				•	
	•				
	<i>*</i> .				
					y *
					3
					4